

# Creosote-Boron Treated Wood GHS Label



## DANGER

### Hazard Statement(s)

- May form combustible dust concentrations in air.
- Causes skin irritation.
- Causes serious eye irritation.
- May cause allergy or asthma symptoms or breathing difficulties if inhaled.
- May cause an allergic skin reaction.
- May cause cancer.
- May cause respiratory irritation.

### Precautionary Statement(s)

#### Prevention

Wear protective gloves/clothing and eye/face protection. Do not breathe dust or vapors. Use only outdoors or in a well-ventilated area. Wash thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Obtain special instructions before use. Do not handle until all safety precautions have been read and understood.

#### Response

IF EXPOSED OR CONCERNED: Get medical advice/attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician. IF ON SKIN: Wash with plenty of water. If skin irritation or rash occurs, seek medical advice/attention. Take off contaminated clothing and wash it before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.

#### Stella-Jones Corporation

Park West One, Suite 500  
1000 Cliff Mine Road  
Pittsburgh, PA 15275  
Phone: 412-325-0202

#### McFarland Cascade Holdings. Inc.

1640 East Marc  
Tacoma, Washington 98421  
Phone: 253-572-3033